
MARION NARROWS CHARTLET 17 DECEMBER 2021
THE DEPTHS SHOWN WITHIN THE BLACK BOXES AND THE COURSE (SHOWN AS A DOTTED RED LINE) DO NOT FORM PART OF A NAUTICAL CHART.
DEPTHS SHOWN ARE IN METRES AT CHART DATUM REDUCED USING HOBART TIDE TABLES.
THIS INFORMATION HAS BEEN OVERLAID ONTO THE CHART BY MARINE AND SAFETY TASMANIA TO PROVIDE GUIDANCE TO MARINERS ABOUT THE SHIFTING CHANNEL AT MARION NARROWS.
THE DATA PROVIDED WAS ACCURATE ON THE ISSUE DATE HOWEVER SAND SHOALS MOVE CONSTANTLY IN THIS AREA AND DIFFERENT DEPTHS MAY BE ENCOUNTERED.
NOTE: VESSEL TRACK IS EAST OF THE ENTRANCE LEADS
THE CROSSING OF COASTAL BARWAYS IN POTENTIALLY DANGEROUS. MARINERS ARE NOT ADVISED TO ATTEMPT TO ENTER BLACKMAN BAY IN HEAVY NORTH-EASTERLIES
JETTY RUINS
SANDBAR LOCATED CLOSE TO CHANNEL BETWEEN No.4 and No.6 BEACONS
THE ENTRANCE LEADS ARE UNLIT TRIANGULAR ORANGE DAY SHAPES
THIS CHARTLET IS NOT TO BE USED FOR NAVIGATION
PRINTING OF THIS CHART MAY ALTER SIZE AND SCALE OF THE BACKGROUND CHART IMAGERY
Marion
Narrows
Blackman
Head
Little
Chinaman
Bay
No7
Unlit
No4
No6
No8
No9
No11
Fl(2)R.5
3.5
4.0
5.0
4.1
4.0
4.7
8.7
6.6
3.2
5.6
3.9
3.6
4.1
6.7
6.0
5.4
4.5
2.9
5.0
4.4
7.3
5.9
ANC
WPA
WPN
XTD
250 m
N